

SHELL MILL
HOLDERS

END MILL
HOLDERS

MILLING
CHUCKS

SHRINK FIT
HOLDERS

COLLET
CHUCKS

RADIAL
COMP.
HOLDERS

DRILL
CHUCKS

TAP
HOLDERS

BLANK
BARS

RETENTION
STUDS

ACCESSORIES

TECHNICAL
INFO.


INDEX



HSK COOLANT TUBES

PART NUMBER	DESCRIPTION
HSK32-CTC	HSK32 Coolant Tubes
HSK40-CTC	HSK40 Coolant Tubes
HSK50-CTC	HSK50 Coolant Tubes
HSK63-CTC	HSK63 Coolant Tubes
HSK80-CTC	HSK80 Coolant Tubes
HSK100-CTC	HSK100 Coolant Tubes

Coolant tubes are used for coolant thru the tool on HSK toolholders. Coolant tubes are a two-piece design utilizing two rubber O-rings.



HSK COOLANT TUBE WRENCHES

PART NUMBER	DESCRIPTION
HSK32-WTC	HSK32 Coolant Tube Wrench
HSK40-WTC	HSK40 Coolant Tube Wrench
HSK50-WTC	HSK50 Coolant Tube Wrench
HSK63-WTC	HSK63 Coolant Tube Wrench
HSK80-WTC	HSK80 Coolant Tube Wrench
HSK100-WTC	HSK100 Coolant Tube Wrench

Coolant tube wrenches are intended for use with slotted coolant tubes.



SPINDLE WIPES

PART NUMBER	DESCRIPTION
SW-30	30 Taper Spindle Wipe
SW-40	40 Taper Spindle Wipe
SW-50	50 Taper Spindle Wipe

Spindle Wipes are an essential tool for precision machining. They assure the most important connection - the one between the spindle and toolholder, is free of contaminants allowing continuous positive contact. Spindle Wipes include a set of standard cleaning (STD) and a set of varnish removal (VRB) blades.